



# Botão Fêmea



| Tabela                  | D  | L  | La | Da | Db  | H  | Dc      |
|-------------------------|----|----|----|----|-----|----|---------|
| Botão termop. 1914 M4   | 20 | 15 | 08 | 14 | 3/8 | 10 | M4x0,70 |
| Botão termop. 1914 M5   | 20 | 15 | 08 | 14 | 3/8 | 10 | M5x0,80 |
| Botão termop. 1914 M6   | 20 | 15 | 08 | 14 | 3/8 | 10 | M6x1,00 |
| Botão termop. 1914 M8   | 20 | 15 | 08 | 14 | 3/8 | 10 | M8x1,25 |
| Botão termop. 1914 3/16 | 20 | 15 | 08 | 14 | 3/8 | 10 | 3/16-24 |
| Botão termop. 1914 1/4  | 20 | 15 | 08 | 14 | 3/8 | 10 | 1/4unc  |
| Botão termop. 1914 5/16 | 20 | 15 | 08 | 14 | 3/8 | 10 | 5/16unc |
| Botão termop. 2516 M5   | 25 | 15 | 09 | 15 | 3/8 | 10 | M5x0,80 |
| Botão termop. 2516 M6   | 25 | 15 | 09 | 15 | 3/8 | 10 | M6x1,00 |
| Botão termop. 2516 M8   | 25 | 15 | 09 | 15 | 3/8 | 10 | M8x1,25 |
| Botão termop. 2516 3/16 | 25 | 15 | 09 | 15 | 3/8 | 10 | 3/16-24 |
| Botão termop. 2516 1/4  | 25 | 15 | 09 | 15 | 3/8 | 10 | 1/4unc  |
| Botão termop. 2516 5/16 | 25 | 15 | 09 | 15 | 3/8 | 10 | 5/16unc |